






Feb.1.2026 Copyright 2026 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
 In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



Recommended PC board hole pattern (mounting side)



Notes 1 The dimensions in parentheses are for reference.



NO.	MATERIAL	FINISH	REMARKS	NO.	MATERIAL	FINISH	REMARKS
3	PHOSPHOR BRONZE		Contact Area : Gold 0.2μm min. Dip Area : TIN-Plating 2μm min. Under Plating : Nickel 2.5μm min.	5	PHOSPHOR BRONZE		Contact Area : Gold 0.2μm min. Dip Area : TIN-Plating 2μm min. Under Plating : Nickel 2.5μm min.
2	PHOSPHOR BRONZE		Contact Area : Gold 0.2μm min. Dip Area : TIN-Plating 2μm min. Under Plating : Nickel 2.5μm min.	4	PHOSPHOR BRONZE		Contact Area : Gold 0.2μm min. Dip Area : TIN-Plating 2μm min. Under Plating : Nickel 2.5μm min.
1	PBT	BLACK	UL94V-0				

UNITS	SCALE	COUNT	DESCRIPTION OF REVISIONS	DESIGNED	CHECKED	DATE
mm	2 : 1	△	APPROVED : HT. YAMAGUCHI 18.06.25 CHECKED : HT. YAMAGUCHI 18.06.25 DESIGNED : TY. EDAGAWA 18.06.25 DRAWN : MK. OOKI 18.06.21			

DRAWING NO.	PART NO.	CODE NO.
EDC-019016-71-21	HIF6A-32DA-1.27DS(71)	CL631-0003-6-71